## Ultra Moto test

- 1. Compressor out of order
- 2. Thick air hose missing to one bike
- 3. Mechanical problem with right brake control on the red bike
- 4. Red gas cover cracked
- 5. Center console fan dissonance
- 6. Left brake constantly on, blue bike
- 7. Left speaker out of order, blue bike
- 8. Calibration lamp out of order, red bike
- 9. Seat vibrator on blue bike is very weak
- 10. Blue bike pulls to the right and can't get any further
- 11. Red bike pulls to the left
- 12. Led sign broken red bike part no U110-735-000
- 13. VR glasses unknown status